



M3 Folding Stock

Item No: GP384

Instruction Manual



1. Reserve 19mm.



2. Screw Cap is for packing only not for assembly.



3. Screw to the pointed direction, make sure the 4 concave parts are staying upward.



4. After fixing it up, the 4 concave parts are still upward.



5. This stock has 4 position.



6. Push the button on the stock, slightly turn it to the right. Push the stock forward until it is locked in the concave.



7. The stock is locked.



8. Procedure Complete!